

## ANNEXURE D

File No. 277.

Dt: 29/4/2025

### Building safety certificate

It is certified that existing building of **Foundation School at Parli vaijnath District-Beed, Maharashtra** is having blocks floors as per details below;

| Details of Blocks in School | Block-1  | Block2            | Block-3  |
|-----------------------------|----------|-------------------|----------|
| No. of floors in the Block  | Ground+2 | Basement+Ground+3 | Ground+1 |

This building is occupied by **Foundation School** have compiled with the Building Safety requirements in accordance with National Building Code Rules and verified by the officers concern of **Public Work Department** on 28/4/2025 in the presence of **Dr. Ritu Total, Principal** and the building premises is fit for occupancy for running school with effect from 29/4/25 for a period of **One** year in accordance with rule and subject to compliance of the specific conditions has appended.

- 1.
  - 2.
  - 3.
  - 4.
- } All Conditions Fulfilled

Issued on 29/4/2025 at **Parli vaijnath**

  
**Sub-Divisional Engineer**  
**Public Works Sub-Division**  
**Parli**

Signature with seal

Name : Vibhute Praliphane Subhase

Designation: Assistant Engineer.

Name & Address of Department/office: P.W.S. division parli

